

FIG. 1




FIG. 2




FIG. 3




FIG. 4

2 / 63




FIG. 5




FIG. 6




FIG. 7A

3 / 63




FIG. 7B




FIG. 7H

4 / 63




FIG. 7C




FIG. 7D






FIG. 7E

5 / 63



6 / 63




FIG. 8A




FIG. 8B

7 / 63




FIG. 9

8 / 63




FIG. 10




FIG. 11

9 / 63




FIG. 12A




FIG. 13A

10 / 63




FIG. 12B




FIG. 13B




FIG. 14

12 / 63




FIG. 15A




FIG. 15B





FIG. 16






FIG. 17B




FIG. 18

17 / 63




FIG. 19




FIG. 20A

19 / 63




FIG 20B




FIG. 20C




FIG. 20D




FIG. 21




FIG. 22




FIG. 23

25 / 63




FIG. 24




FIG. 25




FIG. 26A




FIG. 26C




FIG. 26B




FIG. 26D




FIG. 27A








FIG. 27B



30 / 63




FIG. 29A




FIG. 29B




FIG. 29C




FIG. 29D

31 / 63




FIG. 30A
(Prior Art)




FIG. 30B
(Prior Art)




FIG. 31A
(Prior Art)




FIG. 31B
(Prior Art)

32 / 63

$t=0 ; e_I > e_{II}$




FIG. 32A
(Prior Art)

$t_1 > 0$




FIG. 32B
(Prior Art)

$t_2 > t_1$




FIG. 32C
(Prior Art)

33 / 63




FIG. 33A




FIG. 33B
(PRIOR ART)

34 / 63

FIG. 34A




FIG. 34B




FIG. 34C





FIG. 34D



35 / 63




FIG. 35A




FIG. 35B




FIG. 35C




FIG. 35D




FIG. 35E




FIG. 36A
(Prior Art)




FIG. 36B







FIG. 37A



38 / 63




FIG. 38A




FIG. 38B

39 / 63




FIG. 39




FIG. 40A




FIG. 40B




FIG. 42




FIG. 41




FIG. 43





FIG. 44



43 / 63




FIG. 45B

FIG. 45C




FIG. 46

45 / 63




FIG. 47





FIG. 48

FIG. 49



47 / 63




FIG. 50

48 / 63




FIG. 51




FIG. 52

49 / 63




FIG. 53A




FIG. 53B





FIG. 54A

FIG. 54B







FIG. 54C

FIG. 54D






FIG. 55




FIG. 56A




FIG. 56D




FIG. 56B




FIG. 56E




FIG. 56C




FIG. 56F










FIG. 57

57 / 63



58 / 63



59 / 63




FIG. 61A




FIG. 61B




FIG. 61C




FIG. 61D

60 / 63




FIG. 61E




FIG. 61F

61 / 63




FIG. 62A




FIG. 62B




FIG. 63A




FIG. 63B




FIG. 64

